# PRELIMINARY SUMMARY OF MAP ACTIONS

Community: MARTIN COUNTY Community No: 180479

To assist your community in maintaining the Flood Insurance Rate Map (FIRM), we have summarized below the previously issued Letter of Map Change (LOMC) actions (i.e., Letters of Map Revision (LOMRs) and Letters of Map Amendment (LOMAs)) that will be affected by the preparation of the enclosed revised FIRM panel(s).

### 1. LOMCs Incorporated

The modifications effected by the LOMCs listed below have been reflected on the Preliminary copies of the revised FIRM panels. In addition, these LOMCs will remain in effect until the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
			NO CASES RECORDED		

## 2. LOMCs Not Incorporated

The modifications effected by the LOMCs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because of scale limitations or because the LOMC issued had determined that the lot(s) or structure(s) involved were outside the Special Flood Hazard Area, as shown on the FIRM. These LOMCs will be revalidated free of charge 1 day after the revised FIRM becomes effective through a single revalidation letter that reaffirms the validity of the previous LOMCs.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
LOMA	98-05-1126A	03/04/1998	R.R. 3, WEST RIVER ROAD - SECTION 18	1804790003B	18101C0185D
LOMA	98-05-5392A	08/14/1998	R.R. 3, BOX 280 B (WHITE RIVER ROAD) - SECTION 18	1804790003B	18101C0185D
LOMR-F	04-05-A108A	08/25/2004	PORTION OF SECTION 3, T3N, R3W WILLIAMS ROAD	1804790004B	18101C0225D
LOMA	05-05-4263A	09/07/2005	R.R. 4, BOX 319C PORTION OF SECTION 17, T3N, R4W	1804790003B	18101C0180D
LOMA	09-05-4454A	08/18/2009	PORTION OF SECTION 24, T3N, R4W 12923 WEST RIVER ROAD	1804790003B	18101C0185D 18101C0195D
LOMA	09-05-4745A	09/10/2009	PORTION OF SECTION 24, T3N, R4W 12881 WEST RIVER ROAD	1804790003B	18101C0185D 18101C0195D

5/23/2011 Page 1 of 2

### PRELIMINARY SUMMARY OF MAP ACTIONS

Community: MARTIN COUNTY Community No: 180479

#### 3. LOMCs Superseded

The modifications effected by the LOMCs listed below have not been reflected on the Preliminary copies of the revised FIRM panels because they are being superseded by new detailed flood hazard information or the information available was not sufficient to make a determination. The reason each is being superseded is noted below. These LOMCs will no longer be in effect when the revised FIRM becomes effective.

LOMC	Case No.	Date Issued	Project Identifier	Reason Determination Will be Superseded
			NO CASES RECORDED	

- 1. Insufficient information available to make a determination.
- 2. Lowest Adjacent Grade and Lowest Finished Floor are below the proposed Base Flood Elevation.
- 3. Lowest Ground Elevation is below the proposed Base Flood Elevation.
- 4. Revised hydrologic and hydraulic analyses.
- 5. Revised topographic information.

#### 4. LOMCs To Be Redetermined

The LOMCs in Category 2 above will be revalidated through a single revalidation letter that reaffirms the validity of the determination in the previously issued LOMC. For LOMCs issued for multiple lots or structures where the determination for one or more of the lots or structures has changed, the LOMC cannot be revalidated through this administrative process. Therefore, we will review the data previously submitted for the LOMC requests listed below and issue a new determination for the affected properties after the effective date of the revised FIRM.

LOMC	Case No.	Date Issued	Project Identifier	Old Panel	New Panel
			NO CASES RECORDED		

5/23/2011 Page 2 of 2